

OUT60382

SECRET 150122Z CITE [REDACTED] 9046

15 NOV 1966 01 45 25X1

25X1

1. CAMERA B 15 WAS USED IN MISSION G 925 FLOWN ON 12 NOVEMBER 1966. PROCESSING WAS ACCOMPLISHED AT BARKSDALE.

2. ORIGINAL NEGATIVE

A. THE DENSITY OF THE MATERIAL IS NORMAL AND THE RESOLUTION IS GOOD.

B. 9R SIDE: EDGE STATIC IS PRESENT ALONG BOTH EDGES OF THE FILM THROUGHOUT THE MISSION. A ROW OF MINUS DENSITY DOTS LOCATED 1.0" FROM THE INBOARD EDGE AND 1.7" APART ARE PRESENT THROUGHOUT. VERY MINOR ROLLER CHATTER WAS ALSO NOTED ALONG THE INBOARD EDGE. IN SEVERAL VERTICAL FRAMES THERE IS A VERY SLIGHT CHANGE IN DENSITY APPROXIMATELY 3.0" FROM THE DATA BLOCK. IT IS PROBABLY CAUSED BY EITHER A REFLECTION IN THE WINDOW OR AN INTERNAL CAMERA REFLECTION. THIS ANOMALY HAS BEEN REPORTED BEFORE.

C. 9L SIDE: EDGE STATIC WAS NOTED ALONG BOTH SIDES OF THE MATERIAL. THERE IS ALSO SLIGHT FOGGING INTO THE FORMAT CAUSED BY THE VERTICAL DOT INDICATOR. IT DOES NOT NOTICEABLY DEGRADE THE IMAGERY AND CAN BE SEEN ONLY OVER LOW DENSITY AREAS SUCH AS WATER.

D. BOTH SIDES: THERE WERE A FEW FRAMES NOTED THROUGHOUT THE MISSION THAT WERE SMEARED. THE CAUSE PROBABLY CAN BE ATTRIBUTED TO VEHICLE MANEUVERS. THE LAST TITLED FRAME WAS 2344.

3. POSITIVE

A. PI SUITABILITY IS GOOD.

15 NOV 1966

DISTRIBUTION		
By	Office	Action
1	PTO	
	OS	
	SEC BR	
	TDS	
	GSD	
	IPB	
	PD	
	PSD	
	PSD-ICB	
345	TID	
11	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy  
Sanitized

B. PRINTING AND PROCESSING IS GOOD.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 35 PERCENT OF  
THE MISSION.

S E C R E T

--END OF MESSAGE--

1

1